

US EPA RECORDS CENTER REGION 5



510506

ECOLOGY & ENVIRONMENT, INC.

SME Cement Co.

R05-8601-05A

OH0525

OH D021148630

Date: August 12, 1986

Time: 8:35 am

Weather: Clear, 65° F

People present:

Richard Dagnall E & E

Craig Almanza E & E

Bob Langhall Plant Eng SME

Andy Coccoli Plant Man. SME

The SME Cement Co. produces
Portland Cement

The company has had problems
with brine dumping

The site came to the attention
of the OEPA - NEDO after 30 gallons
of PCB contaminated oil were
spilled when a transformer was
damaged.

The spill was cleaned up and
drummed, but the whereabouts of
the drums is unknown.

No waste

1979 - Installing new switch gear
fork lift damaged transformer
25-30 gal PCB oil spilled
on cement floor

Local agency contacted
dam was made with
cement dust. Dust also
used to soak up oil.
Everything put in 55 gal
drum. Contacted CEKOS,
for disposal.

1983 Bureau of Criminal
Investigation inspection
discovered seeping oil
from a transformer. No
oil hit the ground. Seal
was tightened. Meyers
transformer, out of Akron,
refurbished and cleaned

the transformer. All rags
and oil drummed and removed
by Meyers.

Total waste 25-30 gallons

Permits

Air - All State permits

Local - Sewage

State - Mining

Buildings on Site 25

Area 1200-1500 Acres

50-60

~~1000~~ - operating

No fencing

Current

SME Cement Co.

8282 Middlebranch Rd

P.O. Box 234

Middlebranch, OH 44652

No parent company

Previous owner

Flintkote

White plains N.Y.

Realty Owners

SME Cement Co. Inc.

Current Op

SME Cement Co. Inc.

Previous Op.

Flintcoat

White plains NY

SME 1979 - Present

Flintkote ~~1978-1977~~ 1964-1976

Diamond 1898-1960